



INVESTIGATION REPORT

Building and Safety/Land Development Division

Location of Problem: 14363 ~~Inter~~recita

Locality: Whittier

Description of Problem: Roof removed for
seven months — covered with
plastic. Junk in rear yard.
Watch out for unstable owner?

Requested by: Anonymous.

Request call back after investigation? Yes ☐ No ☐

Received by: Don Date: 7/16/97

Assigned/Referred to: Samme Date: 4/17/97

Report of Investigation: _____

Investigator: _____ Title: _____ Date: _____

Copy Sent to: _____ Title: _____ Date: _____

Report Phoned to: _____ Title: _____ Date: _____



INVESTIGATION REPORT

Building and Safety/Land Development Division

Location of Problem: 14363 Cerecita Dr.

Locality: Whitt

Description of Problem: Re-roof - no permit

Requested by: [Signature]

Request call back after investigation? Yes ☐ No ☐

Received by: [Signature] Date: 1-6-97

Assigned/Referred to: Dan Date: 1-7-97

Report of Investigation: _____

Investigator: _____ Title: _____ Date: _____

Copy Sent to: _____ Title: _____ Date: _____

Report Phoned to: _____ Title: _____ Date: _____

14363 CERECEITA